



NAASCO NORTHEAST CORP.

Enjoy substantial savings over the cost of OEM New with NAASCO's...

Sil-Met™ Repair Solutions

For Power Relays, Contacts and Terminal Boards



REPAIRED CONTACTS
P/N 949B071-1
or
P/N 965C321-1



HAMILTON SUNDSTRAND
942D023-SERIES
for BOEING 747



REPAIRED TERMINAL BOARD
P/N 942D632-1 or 946F429-5

**FAA AND AIRLINE APPROVED
REPAIR PROCESS FOR
INDIVIDUAL CONTACTS AND
RELAY ASSEMBLIES**